

Synchronous Machine Model

Voltage, current, and instantaneous power in abc, $\alpha\beta 0$ and dq0 coordinates

$$MMF_{abc}(\vartheta) = i_a \cos \vartheta + i_b \cos(\vartheta + 2\pi/3) + i_c \cos(\vartheta - 2\pi/3)$$


$$MMF_{\alpha\beta}(\vartheta) = i_\alpha \cos \vartheta + i_\beta \cos(\vartheta + \pi/2)$$

$$MMF_{\alpha\beta}(\vartheta) = MMF_{abc}(\vartheta) \rightarrow$$

$$i_\alpha \cos \vartheta + i_\beta \cos(\vartheta + \pi/2) = i_a \cos \vartheta + i_b \cos(\vartheta + 2\pi/3) + i_c \cos(\vartheta - 2\pi/3)$$

$$\cos(\vartheta + \pi/2) = -\sin \vartheta$$

$$i_\alpha \cos \vartheta - i_\beta \sin \vartheta = i_a \cos \vartheta + i_b \left(-\frac{1}{2} \cos \vartheta - \frac{\sqrt{3}}{2} \sin \vartheta \right) + i_c \left(-\frac{1}{2} \cos \vartheta + \frac{\sqrt{3}}{2} \sin \vartheta \right)$$



Voltage, current, and instantaneous power in abc, $\alpha\beta 0$ and dq0 coordinates

Example:

$$i_a = i_m \cos \omega t$$

$$i_b = i_m \cos(\omega t - 2\pi/3)$$


$$i_c = i_m \cos(\omega t + 2\pi/3)$$

At location $\vartheta = 0$ and time $t = 0$:

$$i_\alpha = i_a + i_b \left(-\frac{1}{2}\right) + i_c \left(-\frac{1}{2}\right) = \frac{3}{2} i_m$$

At location $\vartheta = \pi/2$ and time $\omega t = \pi/2$:

$$i_\beta = -i_b \frac{\sqrt{3}}{2} + i_c \frac{\sqrt{3}}{2} = -\frac{\sqrt{3}\sqrt{3}}{2} \frac{\sqrt{3}}{2} - \frac{\sqrt{3}\sqrt{3}}{2} \frac{\sqrt{3}}{2} = -\frac{3}{2} i_m$$




Amplitude of $i_\alpha : \frac{3}{2} i_m$

Amplitude of $i_\beta : \frac{3}{2} i_m$

$$\longrightarrow i_\alpha \cos \vartheta - i_\beta \sin \vartheta = \frac{2}{3} \left(i_a \cos \vartheta + i_b \left(-\frac{1}{2} \cos \vartheta - \frac{\sqrt{3}}{2} \sin \vartheta\right) + i_c \left(-\frac{1}{2} \cos \vartheta + \frac{\sqrt{3}}{2} \sin \vartheta\right) \right)$$

Amplitudes of both $i_\alpha; i_\beta = i_m$

Voltage, current, and instantaneous power in abc and $\alpha\beta 0$ coordinates



$$i_\alpha \cos \vartheta - i_\beta \sin \vartheta$$

$$= \frac{2}{3} \left(i_a \cos \vartheta + i_b \left(-\frac{1}{2} \cos \vartheta - \frac{\sqrt{3}}{2} \sin \vartheta \right) + i_c \left(-\frac{1}{2} \cos \vartheta + \frac{\sqrt{3}}{2} \sin \vartheta \right) \right)$$

$$i_\alpha = \frac{2}{3} \left(i_a - \frac{1}{2} i_b - \frac{1}{2} i_c \right)$$

$$i_\beta = \frac{2}{3} \left(\frac{\sqrt{3}}{2} i_b - \frac{\sqrt{3}}{2} i_c \right)$$

If the star point is grounded:

$$i_0 = \frac{1}{3} (i_a + i_b + i_c)$$

$$\begin{pmatrix} i_\alpha \\ i_\beta \\ i_0 \end{pmatrix} = \frac{2}{3} \begin{pmatrix} 1 & -\frac{1}{2} & -\frac{1}{2} \\ 0 & \frac{\sqrt{3}}{2} & -\frac{\sqrt{3}}{2} \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{pmatrix} \begin{pmatrix} i_a \\ i_b \\ i_c \end{pmatrix} = \frac{1}{3} \begin{pmatrix} 2 & -1 & -1 \\ 0 & \sqrt{3} & -\sqrt{3} \\ 1 & 1 & 1 \end{pmatrix} \begin{pmatrix} i_a \\ i_b \\ i_c \end{pmatrix}$$

Space phasor

$$i_\alpha = \frac{2}{3} \left(i_a - \frac{1}{2} i_b - \frac{1}{2} i_c \right)$$

$$i_\beta = \frac{2}{3} \left(\frac{\sqrt{3}}{2} i_a - \frac{\sqrt{3}}{2} i_c \right)$$

Space phasor $\underline{I}_{\alpha\beta}^{\angle 0} = i_\alpha + j i_\beta = \frac{2}{3} \left(i_a + i_b \left(-\frac{1}{2} + j \frac{\sqrt{3}}{2} \right) + i_c \left(-\frac{1}{2} - j \frac{\sqrt{3}}{2} \right) \right) = \frac{2}{3} (i_a + i_b \underline{a} + i_c \underline{a}^2)$



Time phasor $u(t) = \sqrt{2} U \cos(\omega t + \varphi_u) = \operatorname{Re} \{ \sqrt{2} U \cos(\omega t + \varphi_u) + j \sqrt{2} U \sin(\omega t + \varphi_u) \}$
 $= \operatorname{Re} \{ \sqrt{2} U \cdot e^{j\varphi_u} e^{j\omega t} \}$

Time phasor $\underline{U} = U \cdot e^{j\varphi_u}$

Space phasor $\underline{U}^{\angle 0} = \frac{2}{3} (u_a + u_b \underline{a} + u_c \underline{a}^2)$

Diference between time & space phasor

Time phasor is function of time



Space phasor w.r.t stationary referencne frame

Space phasor


$$\underline{I}_{\alpha\beta}^{\angle 0} = i_{\alpha} + ji_{\beta} = \frac{2}{3}(i_a + i_b \underline{a} + i_c \underline{a}^2)$$

Example

$$i_a = 5 \cos \omega t \quad i_b = 5 \cos(\omega t - 2\pi/3) \quad i_c = 5 \cos(\omega t + 2\pi/3)$$

$$\begin{pmatrix} i_{\alpha} \\ i_{\beta} \\ i_0 \end{pmatrix} = \frac{1}{3} \begin{pmatrix} 2 & -1 & -1 \\ 0 & \sqrt{3} & -\sqrt{3} \\ 1 & 1 & 1 \end{pmatrix} \begin{pmatrix} 5 \cos \omega t \\ 5 \cos(\omega t - 2\pi/3) \\ 5 \cos(\omega t + 2\pi/3) \end{pmatrix}$$


$$\begin{pmatrix} i_a \\ i_b \\ i_c \end{pmatrix} = \begin{pmatrix} 1 & 0 & 1 \\ -\frac{1}{2} & \frac{\sqrt{3}}{2} & 1 \\ -\frac{1}{2} & -\frac{\sqrt{3}}{2} & 1 \end{pmatrix} \begin{pmatrix} i_{\alpha} \\ i_{\beta} \\ i_0 \end{pmatrix}$$



ωt	0	$\pi/4$	$\pi/2$	$3\pi/4$	π	$5\pi/4$
i_{α}	5	3.54	0	-3.54	-5	-3.54
i_{β}	0	3.54	5	3.54	0	-3.54
$\underline{I}_{\alpha\beta}^{\angle 0}$	$5 \angle 0^{\circ}$	$5 \angle 45^{\circ}$	$5 \angle 90^{\circ}$	$5 \angle 135^{\circ}$	$5 \angle 180^{\circ}$	$5 \angle 225^{\circ}$
	\underline{I}_1	\underline{I}_2	\underline{I}_3	\underline{I}_4	\underline{I}_5	\underline{I}_6

→ Rotates in space with respect to a stationary reference frame

Voltage, current, and instantaneous power in a dq0 coordinates



Space phasor -


$$\underline{I}_{\alpha\beta}^{\angle 0} = i_{\alpha} + j i_{\beta} = \frac{2}{3} \left(i_a + i_b \left(-\frac{1}{2} + j \frac{\sqrt{3}}{2} \right) + i_c \left(-\frac{1}{2} - j \frac{\sqrt{3}}{2} \right) \right) = \frac{2}{3} (i_a + i_b \underline{a} + i_c \underline{a}^2)$$

$$\underline{I}_{dq}^{\angle \omega} = \underline{I}_{\alpha\beta}^{\angle 0} \cdot e^{-j\vartheta} = i_d + j i_q = \frac{2}{3} (i_a + i_b \underline{a} + i_c \underline{a}^2) \cdot e^{-j\vartheta} = \frac{2}{3} (i_a + i_b e^{-j(\vartheta - \frac{2\pi}{3})} + i_c e^{-j(\vartheta + \frac{2\pi}{3})})$$

$$i_d = \frac{2}{3} \left(i_a \cos \vartheta + i_b \cos \left(\vartheta - \frac{2\pi}{3} \right) + i_c \cos \left(\vartheta + \frac{2\pi}{3} \right) \right)$$

$$i_q = \frac{2}{3} \left(-i_a \sin \vartheta - i_b \sin \left(\vartheta - \frac{2\pi}{3} \right) - i_c \sin \left(\vartheta + \frac{2\pi}{3} \right) \right)$$

Voltage, current, and instantaneous power in abc, $\alpha\beta 0$ and dq0 coordinates



$$i_d = \frac{2}{3} (i_a \cos \vartheta + i_b \cos(\vartheta - 2\pi/3) + i_c \cos(\vartheta + 2\pi/3))$$

$$i_q = \frac{2}{3} (-i_a \sin \vartheta - i_b \sin(\vartheta - 2\pi/3) - i_c \sin(\vartheta + 2\pi/3))$$

$$i_0 = \frac{1}{3} (i_a + i_b + i_c)$$

$$\begin{pmatrix} i_d \\ i_q \\ i_0 \end{pmatrix} = \frac{2}{3} \begin{pmatrix} \cos \vartheta & \cos(\vartheta - 2\pi/3) & \cos(\vartheta + 2\pi/3) \\ -\sin \vartheta & -\sin(\vartheta - 2\pi/3) & -\sin(\vartheta + 2\pi/3) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{pmatrix} \begin{pmatrix} i_a \\ i_b \\ i_c \end{pmatrix}$$

Space phasor w.r.t rotating reference frame


Space phasor $\underline{I}_{dq}^{\omega} = i_d + ji_q$

Example

$$i_a = 5 \cos \omega t \quad i_b = 5 \cos(\omega t - 2\pi/3) \quad i_c = 5 \cos(\omega t + 2\pi/3)$$

$$\begin{pmatrix} i_d \\ i_q \\ i_0 \end{pmatrix} = \frac{2}{3} \begin{pmatrix} \cos \vartheta & \cos(\vartheta - 2\pi/3) & \cos(\vartheta + 2\pi/3) \\ -\sin \vartheta & -\sin(\vartheta - 2\pi/3) & -\sin(\vartheta + 2\pi/3) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{pmatrix} \begin{pmatrix} 5 \cos \omega t \\ 5 \cos(\omega t - 2\pi/3) \\ 5 \cos(\omega t + 2\pi/3) \end{pmatrix}$$

$$\vartheta = \omega t$$



ωt	0	$\pi/4$	$\pi/2$	$3\pi/4$	π	$5\pi/4$
i_d	5	5	5	5	5	5
i_q	0	0	0	0	0	0
$\underline{I}_{dq}^{\omega}$	$5 \angle 0^\circ$	$5 \angle 0^\circ$	$5 \angle 0^\circ$	$5 \angle 0^\circ$	$5 \angle 0^\circ$	$5 \angle 0^\circ$
	\underline{I}_1					

→ Stationary in space with respect to a rotating reference frame

abc → αβ0 and abc → dq0

abc → αβ0	abc → dq0
$\begin{pmatrix} g_\alpha \\ g_\beta \\ g_0 \end{pmatrix} = \frac{1}{3} \begin{pmatrix} 2 & -1 & -1 \\ 0 & \sqrt{3} & -\sqrt{3} \\ 1 & 1 & 1 \end{pmatrix} \begin{pmatrix} g_a \\ g_b \\ g_c \end{pmatrix}$	$\begin{pmatrix} g_d \\ g_q \\ g_0 \end{pmatrix} = \frac{2}{3} \begin{pmatrix} \cos \vartheta & \cos(\vartheta - 2\pi/3) & \cos(\vartheta + 2\pi/3) \\ -\sin \vartheta & -\sin(\vartheta - 2\pi/3) & -\sin(\vartheta + 2\pi/3) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{pmatrix} \begin{pmatrix} g_a \\ g_b \\ g_c \end{pmatrix}$
	$\vartheta = \omega t + \vartheta_0$
$p = \frac{3}{2} (u_\alpha i_\alpha + u_\beta i_\beta + 2u_0 i_0)$	$p = \frac{3}{2} (u_d i_d + u_q i_q + 2u_0 i_0)$

g stands for current, voltage, flux (*i*, *u*, *ψ*)

Examples


$$\begin{pmatrix} g_\alpha \\ g_\beta \\ g_0 \end{pmatrix} = \frac{1}{3} \begin{pmatrix} 2 & -1 & -1 \\ 0 & \sqrt{3} & -\sqrt{3} \\ 1 & 1 & 1 \end{pmatrix} \begin{pmatrix} g_a \\ g_b \\ g_c \end{pmatrix} \quad \begin{pmatrix} g_d \\ g_q \\ g_0 \end{pmatrix} = \frac{2}{3} \begin{pmatrix} \cos \vartheta & \cos(\vartheta - 2\pi/3) & \cos(\vartheta + 2\pi/3) \\ -\sin \vartheta & -\sin(\vartheta - 2\pi/3) & -\sin(\vartheta + 2\pi/3) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{pmatrix} \begin{pmatrix} g_a \\ g_b \\ g_c \end{pmatrix}$$

$$i_a = 5 \cos \omega t \quad i_b = 5 \cos(\omega t - 2\pi/3) \quad i_c = 5 \cos(\omega t + 2\pi/3) \quad \vartheta = \vartheta_0 + \omega t$$

$$\begin{pmatrix} i_\alpha \\ i_\beta \\ i_0 \end{pmatrix} = \frac{1}{3} \begin{pmatrix} 2 & -1 & -1 \\ 0 & \sqrt{3} & -\sqrt{3} \\ 1 & 1 & 1 \end{pmatrix} \begin{pmatrix} i_a \\ i_b \\ i_c \end{pmatrix} = \begin{pmatrix} 5 \cos \omega t \\ -5 \sin \omega t \\ 0 \end{pmatrix}$$

$$\begin{pmatrix} i_d \\ i_q \\ i_0 \end{pmatrix} = \frac{2}{3} \begin{pmatrix} \cos \vartheta & \cos(\vartheta - 2\pi/3) & \cos(\vartheta + 2\pi/3) \\ -\sin \vartheta & -\sin(\vartheta - 2\pi/3) & -\sin(\vartheta + 2\pi/3) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{pmatrix} \begin{pmatrix} i_a \\ i_b \\ i_c \end{pmatrix} = \begin{pmatrix} 5 \\ 0 \\ 0 \end{pmatrix}$$

System of equations in per unit



Voltage equations

Stator:

$$u_d = r_a i_d + \frac{d\psi_d}{dt} - \omega \psi_q \quad (1)$$

$$u_q = r_a i_q + \frac{d\psi_q}{dt} + \omega \psi_d \quad (2)$$

Rotor

$$u_F = r_F i_F + \frac{d\psi_F}{dt} \quad (3)$$

$$0 = r_D i_D + \frac{d\psi_D}{dt} \quad (4)$$

$$0 = r_Q i_Q + \frac{d\psi_Q}{dt} \quad (5)$$

Flux equations

Stator

$$\psi_d = L_d i_d + L_{AD} (i_F + i_D) \quad (6)$$

$$\psi_q = L_q i_q + L_{AQ} i_Q \quad (7)$$

Rotor


$$\psi_F = L_F i_F + L_{AD} (i_d + i_D) \quad (8)$$

$$\psi_D = L_D i_D + L_{AD} (i_d + i_F) \quad (9)$$

$$\psi_Q = L_Q i_Q + L_{AQ} i_q \quad (10)$$

- The stator base quantities are based on the machine rating
- The rotor base quantities are chosen so that:
 - the mutual inductances between different circuits are reciprocal (e.g. $L_{Fd} = L_{dF}$) and that the mutual inductances between the rotor and stator circuits in each axis are equal (e.g., $L_{Fd} = L_{Dd}$)
 - The p.u. system is referred to as the " L_{AD} base reciprocal p.u. system"

Synchronous machine sub-transient inductance - L_d''



Assume all rotor windings are short circuited and symmetrical three phase voltage applied such that:

$$\begin{pmatrix} u_a(t) \\ u_b(t) \\ u_c(t) \end{pmatrix} = \sqrt{2} U \begin{pmatrix} \cos(\omega t) \\ \cos(\omega t + 2\pi/3) \\ \cos(\omega t - 2\pi/3) \end{pmatrix} c(t)$$

$c(t) = 0$ for $t < 0$ and $c(t) = 1$ for $t \geq 0$.

$$\begin{pmatrix} u_o \\ u_d \\ u_q \end{pmatrix} = \frac{2}{3} \begin{pmatrix} 1/2 & 1/2 & 1/2 \\ \cos(\omega t) & \cos(\omega t - 2\pi/3) & \cos(\omega t + 2\pi/3) \\ -\sin(\omega t) & -\sin(\omega t - 2\pi/3) & -\sin(\omega t + 2\pi/3) \end{pmatrix} \begin{pmatrix} u_a(t) \\ u_b(t) \\ u_c(t) \end{pmatrix}$$

$$= \sqrt{2} U \begin{pmatrix} 0 \\ c(t) \\ 0 \end{pmatrix} \rightarrow \text{DC voltage applied across coil d.}$$

Eq. (8) & (9):

$$0 = L_F i_F + L_{AD}(i_d + i_D)$$

$$0 = L_D i_D + L_{AD}(i_d + i_F)$$



$$i_D = -\frac{L_F L_{AD} - L_{AD}^2}{L_F L_D - L_{AD}^2} i_d$$

$$i_F = -\frac{L_D L_{AD} - L_{AD}^2}{L_F L_D - L_{AD}^2} i_d$$

Substituted in (6):

$$\psi_d = L_d i_d + L_{AD}(i_F + i_D) = \left(L_d - \frac{L_D L_{AD}^2 + L_F L_{AD}^2 - 2L_{AD}^3}{L_F L_D - L_{AD}^2} \right) \cdot i_d$$

$$\psi_d = L_d'' \cdot i_d \quad L_d'' : \text{the d-axis } \textbf{sub-transient} \text{ inductance}$$

Synchronous machine transient inductance - L_d'

If there is no damper winding in the d-axis, or if the current in the damper winding has decayed to zero, i.e. $i_D = 0$:


$$0 = L_F i_F + L_{AD} i_d \rightarrow i_F = -L_{AD} i_d / L_F$$

$$\psi_d = L_d i_d + L_{AD} (i_F + i_D) = \left(L_d - \frac{L_{AD}^2}{L_F} \right) \cdot i_d$$

$$L_d' = \left(L_d - \frac{L_{AD}^2}{L_F} \right)$$

the d-axis **transient** inductance

Synchronous machine transient inductance - L_q'



Assume all rotor windings are short circuited and symmetrical three phase voltage applied such that:

$$\begin{pmatrix} u_a(t) \\ u_b(t) \\ u_c(t) \end{pmatrix} = \sqrt{2} U \begin{pmatrix} \sin(\omega t) \\ \sin(\omega t + 2\pi/3) \\ \sin(\omega t - 2\pi/3) \end{pmatrix} c(t)$$

$c(t) = 0$ for $t < 0$ and $c(t) = 1$ for $t \geq 0$.

$$\begin{pmatrix} u_o \\ u_d \\ u_q \end{pmatrix} = \frac{2}{3} \begin{pmatrix} 1/2 & 1/2 & 1/2 \\ \cos(\omega t) & \cos(\omega t - 2\pi/3) & \cos(\omega t + 2\pi/3) \\ -\sin(\omega t) & -\sin(\omega t - 2\pi/3) & -\sin(\omega t + 2\pi/3) \end{pmatrix} \begin{pmatrix} u_a(t) \\ u_b(t) \\ u_c(t) \end{pmatrix}$$

$$= \sqrt{2} U \begin{pmatrix} 0 \\ 0 \\ c(t) \end{pmatrix} \rightarrow \text{DC voltage applied across q coil.}$$

Eq. (10) :

$$0 = L_Q i_Q + L_{AQ} i_q \quad \longrightarrow \quad i_Q = -\frac{L_{AQ}}{L_Q} i_q$$

Substituted in (7):

$$\psi_q = L_q i_q + L_{AQ} i_Q = \left(L_q - \frac{L_{AQ}^2}{L_Q} \right) \cdot i_d$$

$$\psi_d = L_q'' \cdot i_q \quad L_q'' : \text{the q-axis } \underline{\text{sub-transient}} \text{ inductance}$$

Synchronous machine inductances

- There is no field winding in the q-axis.
 - For a salient-pole machine with damper winding in the q-axis, the effective inductance after the current in the damper winding has decayed is practically equal to the synchronous inductance
 $\checkmark L'_q = L_q$ (The transient and synchronous inductances in the q-axis are equal)

- General relationship:

$$L_d'' < L_d' < L_d$$
$$L_q'' < L_q' = L_q$$

Synchronous machine open-circuit time constants (T_{do}' , T_{do}'' , T_{qo}')

Assume:

all three stator windings are open-circuited and a step voltage is applied on the field winding, i.e. at $t = 0$, $u_F = U_F c(t)$

The result:

$$u_F = r_F i_F + \frac{d\psi_F}{dt} = U_F c(t)$$

$$0 = r_D i_D + \frac{d\psi_D}{dt}$$

Since $i_d = 0$ (open-circuit):

$$\psi_F = L_F i_F + L_{AD} (i_d + i_D) = L_F i_F + L_{AD} i_D$$

$$\psi_D = L_D i_D + L_{AD} (i_d + i_F) = L_D i_D + L_{AD} i_F$$

Synchronous machine open-circuit time constants (T_{d0}' , T_{d0}'' , T_{q0}')

- Full model (3) – (5) plus the mechanical equations (swing equation):

$$u_F = r_F i_F + \frac{d\psi_F}{dt} \quad (3)$$

$$0 = r_D i_D + \frac{d\psi_D}{dt} \quad (4)$$

$$0 = r_Q i_Q + \frac{d\psi_Q}{dt} \quad (5)$$

- 4th Order model (3), (5) plus the mechanical equations
- Eliminate all parameters from the differential equations except T_{d0}'' , T_{d0}' , T_{q0}'' , x_q'' , x_d'' , x_d'

Synchronous machine open-circuit time constants (T_{do}' , T_{do}'' , T_{qo}')

After the transients in the damper winding D have died down, i.e. $i_D = 0$, the flux linkage is solely determined by the field current. Thus,

$$T_{do}' = \frac{L_F}{r_F}$$

For a synchronous machine with a damper winding in the q-axis:

$$T_{qo}'' = \frac{L_Q}{r_Q}$$

4th Order model of the synchronous machine

q-axis

$$\psi_q = L_q i_q + L_{AQ} i_Q \quad (7)$$

$$\psi_Q = L_Q i_Q + L_{AQ} i_q \quad (10)$$

$$\psi_Q = L_Q i_Q + L_{AQ} i_q \rightarrow i_Q = \frac{\psi_Q - L_{AQ} i_q}{L_Q} \rightarrow \psi_q = L_q i_q + L_{AQ} i_Q \rightarrow \psi_q = L_q i_q + L_{AQ} \frac{\psi_Q - L_{AQ} i_q}{L_Q} \rightarrow$$

$$\psi_q - \frac{L_{AQ}}{L_Q} \psi_Q = i_q \left(L_q - \frac{L_{AQ}^2}{L_Q} \right) = i_q L_q''$$

$$L_q'' = \left(L_q - \frac{L_{AQ}^2}{L_Q} \right)$$

Define: $e_d' = \omega \frac{L_{AQ}}{L_Q} \psi_Q \rightarrow$

$$\psi_q - \frac{e_d'}{\omega} = i_q L_q'' \rightarrow \omega \psi_q = e_d' + i_q x_q''$$

$$\frac{de_d'}{dt} = \omega \frac{L_{AQ}}{L_Q} \frac{d\psi_Q}{dt} \quad (\text{assuming } \frac{d\omega}{dt} = 0)$$

Re-writing (7):

$$x_q i_q + \omega L_{AQ} i_Q - e_d' = i_q x_q'' \rightarrow i_Q = \frac{e_d' - (x_q - x_q'') i_q}{\omega L_{AQ}}$$

$$0 = r_Q i_Q + \frac{d\psi_Q}{dt} \quad (5)$$

$$r_Q i_Q + \frac{d\psi_Q}{dt} = 0 \rightarrow r_Q \frac{e_d' - (x_q - x_q'') i_q}{\omega L_{AQ}} + \frac{L_Q}{\omega L_{AQ}} \frac{de_d'}{dt} = 0$$

$$T_{q0}'' \frac{de_d'}{dt} + e_d' - (x_q - x_q'') i_q = 0$$

$$T_{q0}'' \frac{de_d'}{dt} + e_d' - (x_q - x_q'') i_q = 0$$

$$T_{q0}'' = \frac{L_Q}{r_Q}$$

d-axis

$$\psi_d = L_d i_d + L_{AD}(i_F + i_D) \quad (6)$$

$$\psi_F = L_F i_F + L_{AD}(i_d + i_D) \quad (8)$$

$$\psi_F = L_F i_F + L_{AD} i_d \quad \rightarrow \quad i_F = \frac{\psi_F - L_{AD} i_d}{L_F}$$

($i_D = 0$ in transient phase)

$$\psi_d = L_d i_d + L_{AD} i_F = L_{AD} \frac{\psi_F - L_{AD} i_d}{L_F}$$

$$\psi_d - \frac{L_{AD} \psi_F}{L_F} = \left(L_d - \frac{L_{AD}^2}{L_F} \right) i_d = L'_d i_d \quad \text{With } L'_d = \left(L_d - \frac{L_{AD}^2}{L_F} \right)$$

Define: $e'_q = -\omega \frac{L_{AD}}{L_F} \psi_F \rightarrow \psi_d - \frac{L_{AD} \psi_F}{L_F} = L'_d i_d \rightarrow$

$$\psi_d + \frac{e'_q}{\omega} = i_d L'_d \rightarrow \omega \psi_d = -e'_q + i_d x'_d$$

Substitute in (6): $x_d i_d + \omega L_{AD} i_F + e'_q = i_d x'_d$

$$i_F = \frac{-e'_q - (x_d - x'_d) i_d}{\omega L_{AD}}$$

$$\frac{de'_q}{dt} = -\omega \frac{L_{AD}}{L_F} \frac{d\psi_F}{dt} \quad (\text{assuming } \frac{d\omega}{dt} = 0)$$

$$u_F = r_F i_F + \frac{d\psi_F}{dt} \quad (3)$$

$$u_F = -r_F \frac{e'_q + (x_d - x'_d) i_d}{\omega L_{AD}} - \frac{L_F}{\omega L_{AD}} \frac{de'_q}{dt} \rightarrow \frac{\omega L_{AD} u_F}{r_F} = -e'_q - (x_d - x'_d) i_d - T'_{do} \frac{de'_q}{dt}$$

$$T'_{do} = \frac{L_F}{r_F}$$

With $e_F = \frac{\omega L_{AD} u_F}{r_F}$

$$T'_{do} \frac{de'_q}{dt} + e'_q + (x_d - x'_d) i_d = -e_F$$

Synchronous machine capability curve

Operational limits of synchronous generator

- The loading limits of a synchronous generator are determined by its size and construction, i. e, by:
 - Cooling of the rotor and stator windings,
 - Iron saturation limit,
 - The capacity of the excitation system, etc.
- These technical limits must be observed during operation at all times.
- The operational chart of the synchronous machine shows these boundaries

Operational chart of a synchronous machine

1. **Limit: Maximum armature current**

- The maximum apparent power S is the limit with regard to stator heating
 - This limit is given by the equation:


$$S^2 = P^2 + Q^2 = konst.$$

Minimum/maximum active power limit

2. **Limit: minimum and maximum active power loading**

- For thermal power plants, these limits (P_{\min} , P_{\max}) are determined by the minimum and maximum steam flow through the turbine
- For hydropower generators: $P_{\min} = 0$, and P_{\max} determined by the maximum flow rate of the water.
 - The minimum and maximum deliverable active power, P_{\min} and P_{\max} , are shown as horizontal lines in the operational chart

Active power / armature heating limits



Under excitation limit

3. Limit: Steady state under-excitation limit

$$\underline{I}_a = \frac{U_p - U}{jX_d} = \frac{U_p \angle \delta - U}{jX_d} = \frac{U_p \angle \delta - \pi/2 + jU}{X_d}$$

Up: excitation voltage
U: terminal voltage

$$\underline{S} = 3 \cdot U \cdot \underline{I}_a^* = 3 \cdot U \cdot \frac{U_p \angle -\delta + (\pi/2) - jU}{X_d} = \frac{3 \cdot U \cdot U_p \cdot \sin \delta}{X_d} + j \frac{3 \cdot U \cdot U_p \cdot \cos \delta - U^2}{X_d}$$

$$P = \frac{3 \cdot U \cdot U_p \cdot \sin \delta}{X_d} = \omega_m \cdot M \qquad Q = \frac{3 \cdot U \cdot U_p \cdot \cos \delta - U^2}{X_d}$$

- The theoretical stability limit is $\delta = 90^\circ$.
 - To allow a safety margin, however, a maximum power angle is limited to $\delta_{max} = 70^\circ$ (for example).

Stability limit

$$\sin \delta = \frac{P \cdot X_d}{3 \cdot U \cdot U_p} \qquad \cos \delta = \frac{Q \cdot X_d + U^2}{3 \cdot U \cdot U_p}$$

$$\tan \delta = \frac{P \cdot X_d}{Q \cdot X_d + U^2} \rightarrow P = Q \cdot \tan \delta + \frac{U^2}{X_d} \cdot \tan \delta$$

The stability limit in a Q – P plane (assuming $\delta_{max} = 70^\circ$) is:

- a straight line with the slope: $\tan 70^\circ = 2.75$

- X-intercept:

$$P = 0 \rightarrow Q = -\frac{U^2}{X_d}$$

Minimum/maximum excitation

4. **Limit:** Maximum allowable rotor heating ($U_{P,max}$)

- Most generators are equipped with AVR
- By changing the excitation current, the excitation voltage and thus also the terminal voltage of the generator can be controlled.
- The voltage regulation specifies a minimum excitation voltage $U_{p,min}$.
- The maximum excitation voltage $U_{p,max}$ is predetermined by the maximum permissible heating of the rotor winding.
 - These two limits can be represented in the operating diagram by two circles.

$$\sin \delta = \frac{P \cdot X_d}{3 \cdot U \cdot U_p}$$

$$\cos \delta = \frac{Q \cdot X_d + U^2}{3 \cdot U \cdot U_p}$$

$$\left(\frac{3 \cdot U \cdot U_p}{X_d} \right)^2 = P^2 + \left(Q + \frac{U^2}{X_d} \right)^2$$

Maximum/maximum excitation

Locus:

$$\left(\frac{3 \cdot U \cdot U_p}{X_d} \right)^2 = P^2 + \left(Q + \frac{U^2}{X_d} \right)^2$$

Equation of a circle
with origin:


$$\left(-\frac{U^2}{X_d}, 0 \right)$$

and radius: $\frac{3 \cdot U \cdot U_p}{X_d}$

Minimum excitation $\frac{3 \cdot U \cdot U_{p,MIN}}{X_d}$

Maximum excitation: $\frac{3 \cdot U \cdot U_{p,MAX}}{X_d}$

Operational diagram



Effect of generator reactive power limit


- Voltage instability is typically preceded by generators hitting their upper reactive limit (OXL)
 - Accurate modeling of Q_{\max} is very important for the analysis of voltage instability
- Most power flow programs represent generator Q_{\max} as fixed.
 - However, this is an approximation. In reality, Q_{\max} is not fixed. The generator capability diagram shows quite clearly that Q_{\max} is a function of P and becomes more restrictive as P increases.
 - A first-order approximation (instead of using fixed Q_{\max}) is to model Q_{\max} as a function of P .

EFFECT OF generator reactive power limit

- Q_{\max} is limited by the Over-excitation Limiter (OXL). The field circuit has a rated steady-state field current $I_{f-\max}$, set by field circuit heating limitations. Since heating is proportional to:

$$\int_{\text{overload time}} I_f^2 dt$$

- Small overloads can be tolerated for longer times. Therefore, most modern OXLs are set with a time-inverse characteristic:



- As soon as the OXL acts to limit I_f , then no further increase in reactive power is possible.
- When drawing PV or QV curves, the action of a generator hitting Q_{\max} will manifest itself as a sharp discontinuity in the curve.

Basic countermeasures

- **Basic strategy:**
 - Apply shunt capacitor banks, mainly in distribution and load area transmission substations to minimize reactive power transmission, allowing automatically controlled reactive power reserve at generators
 - Design and operate transmission network for high, flat voltage profile to minimize I^2X losses
- **Switched shunt capacitor banks:**
 - Local or wide-area control
- **Series capacitor banks**
- **Static var compensators or STATCOMs for short-term voltage stability:**
- **Load shedding:**
 - Local undervoltage or wide-area load shedding

Torque

$$t_e \approx p_e = u_d i_d + u_q i_q = -e'_d i_d - e'_q i_q + i_q i_d (x'_d - x''_q) = -e'_q i_q + i_q i_d (x'_d - x''_q)$$


$x''_q \rightarrow x_q$

$$\begin{pmatrix} u_d \\ u_q \end{pmatrix} = - \begin{pmatrix} 0 \\ e'_q \end{pmatrix} + \begin{pmatrix} r_a & -x_q \\ x'_d & r_a \end{pmatrix} \cdot \begin{pmatrix} i_d \\ i_q \end{pmatrix} \quad \begin{pmatrix} u_{dN} \\ u_{qN} \end{pmatrix} = - \begin{pmatrix} 0 \\ e'_q \end{pmatrix} + \begin{pmatrix} r_a & -(x_q + x_e) \\ x'_d + x_e & r_a \end{pmatrix} \cdot \begin{pmatrix} i_d \\ i_q \end{pmatrix}$$

Incorporating the network

$$t_e \approx p_e = u_d i_d + u_q i_q = -e'_d i_d - e'_q i_q + i_q i_d (x'_d - x''_q) = -e'_q i_q + i_q i_d (x'_d - x''_q)$$

$x''_q \rightarrow x_q$



$$\begin{pmatrix} u_d \\ u_q \end{pmatrix} = - \begin{pmatrix} 0 \\ e'_q \end{pmatrix} + \begin{pmatrix} r_a & -x_q \\ x'_d & r_a \end{pmatrix} \cdot \begin{pmatrix} i_d \\ i_q \end{pmatrix} \quad \begin{pmatrix} u_{dN} \\ u_{qN} \end{pmatrix} = - \begin{pmatrix} 0 \\ e'_q \end{pmatrix} + \begin{pmatrix} r_a & -(x_q + x_e) \\ x'_d + x_e & r_a \end{pmatrix} \cdot \begin{pmatrix} i_d \\ i_q \end{pmatrix}$$

Fourth Order Model

$$T_{q0}'' \frac{de'_d}{dt} + e'_d - (x_q - x_q'') i_q = 0$$

$$T'_{do} \frac{de'_q}{dt} + e'_q + (x_d - x_d') i_d = -e_F$$

$$\frac{d\delta}{dt} = \omega - \omega_0$$

$$\frac{d\omega}{dt} = \frac{\pi f}{H} (p_m - D \omega - p_e)$$

$$t_e \approx p_e = u_d i_d + u_q i_q = -e'_d i_d - e'_q i_q + i_q i_d (x'_d - x_q'')$$